REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Semi-Annual	**Date:**	8/19/2021	**Time:**	9:30 AM
Name of School Corporation:	HONEY GROVE EDUCATIONAL DAYCARE			**Corp ID:**	41001Z
Address of School Corporation:	1709 S SR 135				
City:	Greenwood	**Zip:**	46143	**County Number:**	41
VIN:	1GBHG31RXX1146766	**License Number:**	B958AB	**Bus Number:**	2
Make of Body:	Chevrolet **Year:** 1999	**Make of Chassis:**	Chevrolet	**Year:**	1999
Bus Type:		**Mileage:**	129132		
Inspection Status:	R	**Inspected By:**	Jeff Kastenschmidt	**PE:**	5805

Violations - Rejected

Inspection Code	Description
20-1-4	Rubber seals are missing or loose
29-1-1	The flooring is improper
64-1-4	Any front turn signal does not function properly

Violations - Out of Service

Inspection Code	Description

Bus Type Description