REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Re-Inspection	**Date:**	8/24/2021	**Time:**	11:36 AM
Name of School Corporation:	FRANKLIN COMM. SCHOOL CORP.			**Corp ID:**	414225
Address of School Corporation:	750 E SR 44				
City:	Franklin	**Zip:**	46131	**County Number:**	41
VIN:	4DRBWAAR87A396950	**License Number:**	30613	**Bus Number:**	158
Make of Body:	IC Corporation **Year:** 2006	**Make of Chassis:**	IC Corporation	**Year:**	2007
Bus Type:	D	**Mileage:**	13274		
Inspection Status:	O	**Inspected By:**	Joel Flores	**PE:**	7415

Violations - Rejected

Inspection Code	Description
41-1-2	Any interior protrusions have sharp edges or corners
57-1-2	Step-well area is weakened
57-1-1	Step covering is loose, buckled, or made of a material other than rubber (i.e. rugs, carpets, mats, etc.)

Violations - Out of Service

Inspection Code	Description
7-2-3	The required low air-pressure warning device fails to operate properly

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.