

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Re-Inspection	Date:	8/24/2021	Time:	11:36 AM		
Name of School Corporation:	FRANKLIN COMM. SCHOOL CORP.			Corp ID:	414225		
Address of School Corporation:	750 E SR 44						
City:	Franklin	Zip:	46131	County Number:	41		
VIN:	4DRBWAAR87A396950		License Number:	30613	Bus Number:	158	
Make of Body:	IC Corporation	Year:	2006	Make of Chassis:	IC Corporation	Year:	2007
Bus Type:	D			Mileage:	13274		
Inspection Status:	O	Inspected By:	Joel Flores	PE:	7415		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
41-1-2	Any interior protrusions have sharp edges or corners
57-1-2	Step-well area is weakened
57-1-1	Step covering is loose, buckled, or made of a material other than rubber (i.e. rugs, carpets, mats, etc.)

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
7-2-3	The required low air-pressure warning device fails to operate properly

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.