

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Re-Inspection	<b>Date:</b>	8/25/2021	<b>Time:</b>	10:28 AM		
<b>Name of School Corporation:</b>	SOUTHEAST DUBOIS CO. SCH. CORP			<b>Corp ID:</b>	192100		
<b>Address of School Corporation:</b>	432 E 15th St						
<b>City:</b>	Ferdinand	<b>Zip:</b>	47532	<b>County Number:</b>	19		
<b>VIN:</b>	1GDL7T1D6YJ500810	<b>License Number:</b>	B831H	<b>Bus Number:</b>	17		
<b>Make of Body:</b>	GMC	<b>Year:</b>	1999	<b>Make of Chassis:</b>	Blue Bird Corporation	<b>Year:</b>	1999
<b>Bus Type:</b>	B	<b>Mileage:</b>	143686				
<b>Inspection Status:</b>	R	<b>Inspected By:</b>	Philip Lubbers	<b>PE:</b>	7703		

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

### Bus Type Description

Type B School Bus - A conversion or body constructed and installed upon a van or front-section vehicle chassis or stripped chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. Part of the engine is beneath and/or behind the windshield and beside the driver's seat. The entrance door is behind the front wheels.