

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	8/25/2021	Time:	10:02 AM
Name of School Corporation:	GREENCASTLE COMMUNITY CORP.			Corp ID:	676755
Address of School Corporation:	PO Box 480				
City:	Greencastle	Zip:	46135	County Number:	67
VIN:	1BABKBPA5BF278528	License Number:	2776	Bus Number:	20
Make of Body:	Blue Bird Corporation	Year:	2011	Make of Chassis:	Blue Bird Corporation
Bus Type:	D	Mileage:	65306	Year:	2011
Inspection Status:	O	Inspected By:	Byron Goodman	PE:	7008

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.