

## REPORT OF SCHOOL BUS INSPECTION

|                                       |                           |                        |           |                         |                         |
|---------------------------------------|---------------------------|------------------------|-----------|-------------------------|-------------------------|
| <b>Type of Inspection:</b>            | Semi-Annual               | <b>Date:</b>           | 9/1/2021  | <b>Time:</b>            | 8:04 AM                 |
| <b>Name of School Corporation:</b>    | SILVER CREEK SCHOOL CORP. | <b>Corp ID:</b>        |           |                         | 0945                    |
| <b>Address of School Corporation:</b> | 601 RENZ AVE              |                        |           |                         |                         |
| <b>City:</b>                          | SELLERSBURG               | <b>Zip:</b>            | 47172     | <b>County Number:</b>   | 10                      |
| <b>VIN:</b>                           | 1GBHG31V161233290         | <b>License Number:</b> | 19732     | <b>Bus Number:</b>      | SC5                     |
| <b>Make of Body:</b>                  | Chevrolet                 | <b>Year:</b>           | 2006      | <b>Make of Chassis:</b> | Collins Bus Corporation |
| <b>Bus Type:</b>                      | A2                        | <b>Mileage:</b>        | 89456     | <b>Year:</b>            | 2006                    |
| <b>Inspection Status:</b>             | O                         | <b>Inspected By:</b>   | Troy Boyd | <b>PE:</b>              | 5171                    |

### Violations - Rejected

#### Inspection Code Description

### Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u>  |
|------------------------|---|
| 70-2-4                 | Audible warning device, when required, is not working properly. Buzzers are required after 5-2-94 |
| 20-2-1                 | Is no audible signal when the emergency door is open and ignition switch is on                    |

### Bus Type Description

**Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:**

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.