## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: AnnualDate:9/8/2021Time:9:15 AMName of School Corporation:CULVER COMMUNITY SCHOOLS CORP.Corp ID:505455

Address of School Corporation: PO Box 231

City:CulverZip:46511County Number:50VIN:4DRBUSKP4EB774200License Number:2482Bus Number:09Make of Body:IC Corporation Year:2014

Bus Type: C Mileage: 72817

Inspection Status: R Inspected By: Travis Harrold PE: 8022

## Violations - Rejected

## <u>Inspection Code</u> <u>Description</u>

65-1-1 Any lens is cracked, broken or discolored

13-1-1 Any clearance light is missing, cracked, faded, wrong color, or inoperative

**Violations - Out of Service** 

**Inspection Code Description** 

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.