

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Post-Crash Inspection **Date:** 9/13/2021 **Time:** 9:23 AM
Name of School Corporation: MONROE COUNTY COMM. SCH. CORP. **Corp ID:** 535740
Address of School Corporation: 505 E North Dr
City: Bloomington **Zip:** 47401 **County Number:** 53
VIN: 4DRBUC8N2HB474946 **License Number:** 13066 **Bus Number:** 57
Make of Body: IC Corporation **Year:** 2016 **Make of Chassis:** IC Corporation **Year:** 2017
Bus Type: C **Mileage:** 72412
Inspection Status: O **Inspected By:** Mark Raper **PE:** 6473

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.