

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Post-Crash Inspection	Date: 9/13/2021	Time: 9:23 AM
Name of School Corporation: MONROE COUNTY COMM. SCH. CORP.	Corp ID: 535740	
Address of School Corporation: 505 E North Dr		
City: Bloomington	Zip: 47401	County Number: 53
VIN: 4DRBUC8N2HB474946	License Number: 13066	Bus Number: 57
Make of Body: IC Corporation	Year: 2016	Make of Chassis: IC Corporation
Year: 2017	Mileage: 72412	PE: 6473
Bus Type: C	Inspected By: Mark Raper	
Inspection Status: O		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.