

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Re-Inspection	<b>Date:</b> 9/13/2021	<b>Time:</b> 9:34 AM
<b>Name of School Corporation:</b> ROOTED SCHOOL	<b>Corp ID:</b>	
<b>Address of School Corporation:</b> 5750 E. 30th Street		
<b>City:</b> Indianapolis	<b>Zip:</b> 46218	<b>County Number:</b> 49
<b>VIN:</b> 4DRBUAAN3DB248116	<b>License Number:</b>	<b>Bus Number:</b> 3
<b>Make of Body:</b> IC Corporation	<b>Year:</b> 2013	<b>Make of Chassis:</b> IC Corporation
<b>Year:</b> 2013	<b>Mileage:</b> 55851	<b>Year:</b> 2013
<b>Bus Type:</b> C	<b>Inspected By:</b> Jeff Kastenschmidt	<b>PE:</b> 5805
<b>Inspection Status:</b> O		

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
49-1-1	The reflective material is placed anywhere other than on the front and rear, or both, of the bus between the warning lamps; each side beltline, seat line, or floor line or all three (3); outlining each required emergency exit; or across the rear of the bus directly above the rear bumper.
30-1-1	There are any holes in the floor

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
7-2-1	There is no brake certification form the certification is expired or is not signed within the six-month requirement
50-2-2	The seat belt cutter does not have a full width handgrip, with a protective blade to minimize risk

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**