## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: AnnualDate:9/2/2021Time:10:59 AMName of School Corporation: EAST GIBSON SCHOOL CORPORATIONCorp ID:262725

Address of School Corporation: 941 S Franklin St

City:Oakland CityZip:47660County Number:26VIN:1GB6G3AG8A1145550License Number:2370Bus Number:21Make of Body:Star Trans Year:2010Make of Chassis:Chevrolet Year:2010

Bus Type: Mileage: 102910

Inspection Status: A Inspected By: Bradley Miller PE: 7809

**Violations - Rejected** 

**Inspection Code Description** 

**Violations - Out of Service** 

**Inspection Code Description** 

**Bus Type Description**