REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: AnnualDate:9/2/2021Time:11:08 AMName of School Corporation: EAST GIBSON SCHOOL CORPORATIONCorp ID:262725

Address of School Corporation: 941 S Franklin St

City:Oakland CityZip:47660County Number:26VIN:1GB6G3AG8A1165037License Number:2369Bus Number:22Make of Body:Star Trans Year:2010Make of Chassis:Chevrolet Year:2010

Bus Type: Mileage: 115498

Inspection Status: A Inspected By: Bradley Miller PE: 7809

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection Code Description

Bus Type Description