

## REPORT OF SCHOOL BUS INSPECTION

**Type of Inspection:** Semi-Annual      **Date:** 9/15/2021      **Time:** 10:06 AM  
**Name of School Corporation:** SOUTH HARRISON COMM. SCH. CORP      **Corp ID:** 313190  
**Address of School Corporation:** 315 S Harrison Dr  
**City:** Corydon      **Zip:** 47112      **County Number:** 31  
**VIN:** 4DRBRABNX4B961272      **License Number:** E596217      **Bus Number:** 11  
**Make of Body:** IC Corporation      **Year:** 2004      **Make of Chassis:** IC Corporation      **Year:** 2004  
**Bus Type:** C      **Mileage:** 108333  
**Inspection Status:** O      **Inspected By:** Troy Boyd      **PE:** 5171

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired
64-1-4	Any front turn signal does not function properly

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
64-2-1	Any rear turn signal does not function properly

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**