

REPORT OF SCHOOL BUS INSPECTION

| | | | | | |
|--------------------------------|--------------------------------|-----------------|-----------|------------------|-----------|
| Type of Inspection: | Semi-Annual | Date: | 9/16/2021 | Time: | 9:47 AM |
| Name of School Corporation: | SOUTH HARRISON COMM. SCH. CORP | Corp ID: | 313190 | | |
| Address of School Corporation: | 315 S Harrison Dr | | | | |
| City: | Corydon | Zip: | 47112 | County Number: | 31 |
| VIN: | 1GBJG316391112825 | License Number: | 77648 | Bus Number: | A5 |
| Make of Body: | Collins Bus Corporation | Year: | 2009 | Make of Chassis: | Chevrolet |
| Bus Type: | A2 | Mileage: | 42085 | Year: | 2009 |
| Inspection Status: | O | Inspected By: | Troy Boyd | PE: | 5171 |

Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|---|
| 23-1-3 | Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted). |

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.