

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	9/21/2021	Time:	4:17 PM
Name of School Corporation:	FIRST STUDENT - INDPLS	Corp ID:	4981		
Address of School Corporation:	xxx				
City:	Indianapolis	Zip:	46202	County Number:	49
VIN:	4UZABRFC8MCMN7465	License Number:	549		
Make of Body:	Thomas Built Buses, Inc.	Year:	2020	Make of Chassis:	Thomas Built Buses, Inc.
Bus Type:	C	Mileage:	17133		
Inspection Status:	O	Inspected By:	Jeff Kastenschmidt	PE:	5805

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
7-1-3	Air leak at proper connection
72-1-3	See Notes: Any defect inspector deems a violation not listed
41-1-5	There are loose items that would create a hazard. (Broom, Scraper, Items on dash etc.)
3-1-9	See Notes: Any defect inspector deems a violation not listed
36-1-3	See Notes: Any defect inspector deems a violation not listed

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
4-2-1	Any body clamp is broken or missing
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.