

## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	9/27/2021	Time:	9:51 AM		
Name of School Corporation:	MARION COMMUNITY SCHOOLS			Corp ID:	272865		
Address of School Corporation:	826 E 30th St						
City:	Marion	Zip:	46952	County Number:	27		
VIN:	4DRBUC8NXHB232101		License Number:	10545	Bus Number:	98	
Make of Body:	IC Corporation	Year:	2015	Make of Chassis:	IC Corporation	Year:	2017
Bus Type:	C			Mileage:	60917		
Inspection Status:	O	Inspected By:	Randy McPike	PE:	7018		

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.
28-1-4	The first aid kit is not complete: One (1) package adhesive bandages; containing a total of sixteen (16) 1" x 3" bandages, 1 roll 1"x5yd, 1 blunt scissor, 6 3x3" gauze pads (sterile), 4 2"x5yd gauze stretch material (nonsterile), 3 oval eye pads (sterile), 2 triangular bandages, 1 instruction.

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
18-2-2	Universal Joint: any independent vertical movement between opposing yoke ends great than one eight (1/8) inch, any missing universal joint bearing cap, any missing, broken or loose universal joint bearing cap
64-2-1	Any rear turn signal does not function properly

### Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.