

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Post-Crash Inspection	Date: 9/27/2021	Time: 9:51 AM
Name of School Corporation: MARION COMMUNITY SCHOOLS	Corp ID: 272865	
Address of School Corporation: 826 E 30th St		
City: Marion	Zip: 46952	County Number: 27
VIN: 4DRBUC8NXHB232101	License Number: 10545	Bus Number: 98
Make of Body: IC Corporation	Year: 2015	Make of Chassis: IC Corporation
Year: 2017	Mileage: 60917	PE: 7018
Bus Type: C	Inspected By: Randy McPike	
Inspection Status: O		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.
28-1-4	The first aid kit is not complete: One (1) package adhesive bandages; containing a total of sixteen (16) 1" x 3" bandages, 1 roll 1"x5yd, 1 blunt scissor, 6 3x3" gauze pads (sterile), 4 2"x5yd gauze stretch material (nonsterile), 3 oval eye pads (sterile), 2 triangular bandages, 1 instruction.

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
18-2-2	Universal Joint: any independent vertical movement between opposing yoke ends greater than one eighth (1/8) inch, any missing universal joint bearing cap, any missing, broken or loose universal joint bearing cap
64-2-1	Any rear turn signal does not function properly

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.