

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	9/27/2021	Time:	10:04 AM
Name of School Corporation:	MARION COMMUNITY SCHOOLS	Corp ID:			272865
Address of School Corporation:	826 E 30th St				
City:	Marion	Zip:	46952	County Number:	27
VIN:	1BAKGCSA3MF371596	License Number:	23673	Bus Number:	29
Make of Body:	Blue Bird Corporation	Year:	2019	Make of Chassis:	Blue Bird Corporation
Bus Type:	C	Mileage:	9269	Year:	2021
Inspection Status:	O	Inspected By:	Randy McPike	PE:	7018

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
25-1-1	Mirror or mirror backs that are loose or improperly mounted

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.