REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspectio	n	Date:	9/28/2021	Time:	9:17 AM
Name of School Co	orporation: NOR	TH JUDSON-SA	N PIERRE SCH CO	C	Corp ID:	757515
Address of School Corporation: 801 Campbell Dr						
City:	North Judson	Zip:	46366		County Number:	75
VIN:	4DRBUC8P7FB1437	15	License Number:	8235	Bus Number:	23
Make of Body:	IC Corporation Year:	2014	Make of Chassis:	IC Corporation	Year:	2015
Bus Type:	С		Mileage:	58500		
Inspection Status:	0	Inspected By:	Nathan Sherer		PE:	7029

Violations - Rejected

Inspection Code	Description
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.
62-1-2	One (1) taillight or one (1) brake light does not function

Violations - Out of Service

Inspection Code	Description
20-2-2	Door glass is missing
64-2-1	Any rear turn signal does not function properly
8-2-1	There is no brake certification, or the certification has expired or is not signed

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.