

## REPORT OF SCHOOL BUS INSPECTION

**Type of Inspection:** Semi-Annual      **Date:** 9/28/2021      **Time:** 9:09 AM  
**Name of School Corporation:** BLUE RIVER SERVICES      **Corp ID:** 450001  
**Address of School Corporation:** 3141 Progress Blvd.  
**City:** Corydon      **Zip:** 47112      **County Number:** 31  
**VIN:** 1GBJG31U251224377      **License Number:** 68589      **Bus Number:** 94  
**Make of Body:** Chevrolet      **Year:** 2005      **Make of Chassis:** Chevrolet      **Year:** 2005  
**Bus Type:** A2      **Mileage:** 145126  
**Inspection Status:** O      **Inspected By:** Troy Boyd      **PE:** 5171

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
69-1-3	Wiper blades are torn, cracked, brittle or otherwise deteriorated

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

### Bus Type Description

**Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:**

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.