REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Semi-Annual		**Date:**	9/29/2021	**Time:**	9:33 AM
Name of School Corporation:	SCHOOL CITY OF EAST CHICAGO				**Corp ID:**	454670
Address of School Corporation:	1401 E 144th St					
City:	East Chicago	**Zip:**	46312		**County Number:**	45
VIN:	4DRBUAAP9BB278543		**License Number:**	74213	**Bus Number:**	3
Make of Body:	IC Corporation	**Year:** 2009	**Make of Chassis:**	IC Corporation	**Year:**	2010
Bus Type:	C		**Mileage:**	102037		
Inspection Status:	R	**Inspected By:**	Nathan Sherer		**PE:**	7029

Violations - Rejected

Inspection Code	Description
28-1-4	The first aid kit is not complete: One (1) package adhesive bandages; containing a total of sixteen (16) 1" x 3" bandages, 1 roll 1”x5yd, 1 blunt scissor, 6 3x3” gauze pads (sterile), 4 2”x5yd gauze stretch material (nonsterile), 3 oval eye pads (sterile), 2 triangular bandages, 1 instruction.

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.