

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Registration **Date:** 10/4/2021 **Time:** 8:34 AM
Name of School Corporation: RSI TRUCK & BUS REPAIR, INC **Corp ID:** 45005Z
Address of School Corporation: 3333 Sheffield Ave
City: Hammond **Zip:** 46327 **County Number:** 45
VIN: 4DRBUSKN79B673978 **License Number:** **Bus Number:** 3
Make of Body: AmTran **Year:** 2007 **Make of Chassis:** IC Corporation **Year:** 2009
Bus Type: C **Mileage:** 94557
Inspection Status: O **Inspected By:** Nathan Sherer **PE:** 7029

Violations - Rejected

Inspection Code Description

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
32-2-1	There is fuel leaking from any point on in the fuel system

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.