

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	10/8/2021	Time:	10:26 AM		
Name of School Corporation:	NORTH DAVIESS CO. COMM. SCHOOL			Corp ID:	141375		
Address of School Corporation:	5494 E SR 58						
City:	Elnora	Zip:	47529	County Number:	14		
VIN:	1BAKGCKH19F254913	License Number:	B584R	Bus Number:	10		
Make of Body:	Blue Bird Corporation	Year:	2007	Make of Chassis:	Blue Bird Corporation	Year:	2009
Bus Type:	C	Mileage:	108105				
Inspection Status:	O	Inspected By:	Philip Lubbers	PE:	7703		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
11-1-7	See Notes: Any defect inspector deems a violation not listed

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
25-2-1	Mountings are broken or bent badly enough to inhibit proper adjustment

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.