# **REPORT OF SCHOOL BUS INSPECTION**

Type of Inspection:	Semi-Annual		Date:	10/12/2021	Time:	9:56 AM
Name of Schoo Address of Sch	I Corporation: GR ool Corporation:	REATER JASPE 1520 Saint	ER CONS. SCHC Charles St	OOLS	Corp ID:	192120
City:	Jasper	Zip:	47546		County Number:	19
VIN:	1T88R3E2X81103113		License Number:	91241	Bus Number:	20
Make of Body:	Thomas Built Buses, Yea	<b>ar</b> : 2007	Make of Chassis:	Thomas Built Buses, Inc.	Year:	2008
Bus Type:	D		Mileage:	98717		
Inspection Status:	R	Inspected By:	Philip Lubbers		PE:	7703

## **Violations - Rejected**

Inspection <u>Code</u>	Description
65-1-1	Any lens is cracked, broken or discolored
23-1-2	Any component has deteriorated and allows the escape of exhaust gases (with the engine idling and the system unrestricted)
23-1-3	Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).
70-1-10	If the emergency window instructions are illegible or missing. Must be within 6 inches of the release handle

### Violations - Out of Service

### Inspection Code Description

### Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.