REPORT OF SCHOOL BUS INSPECTION

| Type of Inspection: | Semi-Annual | | | Date: | 10/14/2021 | Time: | 11:31 AM |
|--------------------------------|--------------------------|------------------------------|------------------|---------------------|--------------|-------------------|-------------|
| Name of School Corporation: | | HOLY TRINITY CATHOLIC SCHOOL | | | Corp ID: | 19A865 | |
| Address of School Corporation: | | | 990 Church Ave | | | | |
| City: | Jasper | | Zip: | 47546 | | County Number: | 19 |
| VIN: | 4UZ3CJAA0YCF263 | 302 | | License Number: | B110L | Bus Number: | 2 |
| Make of Body: | Blue Bird Corporation | Year: | : 1999 | Make of Chassis: | Freightliner | Year: | 2000 |
| Bus Type: | С | | | Mileage: | Unknown | | |
| Inspection Status | : R | | Inspected By: | Philip Lubbers | | PE: | 7703 |

Violations - Rejected

| Inspection Code | Description |
|--------------------|--|
| 46-1-5 | Upholstery or padding is ripped, torn, or improperly repaired |
| 70-1-10 | If the emergency window instructions are illegible or missing. Must be within 6 inches of the release handle |

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.