

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Semi-Annual	<b>Date:</b>	10/14/2021	<b>Time:</b>	11:36 AM	
<b>Name of School Corporation:</b>	HOLY TRINITY CATHOLIC SCHOOL	<b>Corp ID:</b>	19A865			
<b>Address of School Corporation:</b>	990 Church Ave					
<b>City:</b>	Jasper	<b>Zip:</b>	47546	<b>County Number:</b>	19	
<b>VIN:</b>	1BABKCPA68F250641	<b>License Number:</b>	B870K	<b>Bus Number:</b>	3	
<b>Make of Body:</b>	Blue Bird Corporation	<b>Year:</b>	2007	<b>Make of Chassis:</b>	Freightliner	
<b>Bus Type:</b>	C	<b>Mileage:</b>	Unknown		<b>Year:</b>	2008
<b>Inspection Status:</b>	R	<b>Inspected By:</b>	Philip Lubbers	<b>PE:</b>	7703	

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
23-1-2	Any component has deteriorated and allows the escape of exhaust gases (with the engine idling and the system unrestricted)
23-1-3	Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).
65-1-1	Any lens is cracked, broken or discolored

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

### Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.