

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Semi-Annual **Date:** 10/25/2021 **Time:** 8:09 AM
Name of School Corporation: BLUE RIVER VALLEY SCHOOLS **Corp ID:** 333405
Address of School Corporation: PO Box 217
City: Mount Summit **Zip:** 47361 **County Number:** 33
VIN: 4UZAAXC537CW45091 **License Number:** 30306 **Bus Number:** 14
Make of Body: Mid Bus, Inc. **Year:** 2006 **Make of Chassis:** Freightliner **Year:** 2006
Bus Type: C **Mileage:** 111697
Inspection Status: O **Inspected By:** Jeremy Mason **PE:** 8139

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
41-1-4	There is debris in the bus. (needs cleaned/includes dirt)
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
64-2-1	Any rear turn signal does not function properly

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.