## **REPORT OF SCHOOL BUS INSPECTION**

Type of Inspection:	: Semi-Annual		Date:	10/25/2021	Time:	8:11 AM
Name of School Co	orporation: BLU	E RIVER VALLE	Y SCHOOLS		Corp ID:	333405
Address of School Corporation: PO Box 217						
City:	Mount Summit	Zip:	47361		<b>County Number:</b>	33
VIN:	1UZABRCS88CY4	5720	License Number:	30828	Bus Number:	17
Make of Body:	Mid Bus, Inc. Year	: 2006	Make of Chassis:	Freightliner	Year:	2006
Bus Type:	С		Mileage:	60830		
Inspection Status:	R	Inspected By:	Jeremy Mason		PE:	8139

## **Violations - Rejected**

Inspection Code	Description
41-1-4	There is debris in the bus. (needs cleaned/includes dirt)
23-1-2	Any component has deteriorated and allows the escape of exhaust gases (with the engine idling and the system unrestricted)
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired

## **Violations - Out of Service**

Inspection Code Description

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.