REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Semi-Annual			Date:	10/25/2021	Time:	11:50 AM
Name of School Corporation: Address of School Corporation:		NORTH DAVIESS CO. COMM. SCHOOL 5494 E SR 58			Corp ID:	141375	
City:	Elnora	Zip:		47529		County Number:	14
VIN:	1BAKFCKH56F233	3657		License Number:	B590C	Bus Number:	3
Make of Body:	Blue Bird Corporation	Year: 2005		Make of Chassis:	Blue Bird Corporation	Year:	2006
Bus Type:	С			Mileage:	Unknown		
Inspection Status:	R	Inspe By:	ected	Philip Lubbers		PE:	7703

Violations - Rejected

Inspection Code	<u>Description</u>
46-1-3	Any required padding is missing
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired
70-1-10	If the emergency window instructions are illegible or missing. Must be within 6 inches of the release handle
44-1-1	Any marker light or lens is missing, cracked, faded, wrong color, or inoperative

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.