

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Semi-Annual **Date:** 10/25/2021 **Time:** 12:10 PM
Name of School Corporation: NORTH DAVIESS CO. COMM. SCHOOL **Corp ID:** 141375
Address of School Corporation: 5494 E SR 58
City: Elnora **Zip:** 47529 **County Number:** 14
VIN: 4DRBRABP13A955902 **License Number:** B208E **Bus Number:** 6
Make of Body: IC Corporation **Year:** 2002 **Make of Chassis:** IC Corporation **Year:** 2003
Bus Type: C **Mileage:** Unknown
Inspection Status: O **Inspected By:** Philip Lubbers **PE:** 7703

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
8-1-4	See Notes: Any defect inspector deems a violation not listed
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired
70-1-10	If the emergency window instructions are illegible or missing. Must be within 6 inches of the release handle
82-1-2	See Notes: Any defect inspector deems a violation not listed

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
8-2-5	There is brake fluid leaking at any point
55-2-4	Tie rod end movement is greater than 1/8 inch (rotational movement is acceptable)
25-2-1	Mountings are broken or bent badly enough to inhibit proper adjustment
25-2-2	Reflective glass is cracked, broken, or missing

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.