REPORT OF SCHOOL BUS INSPECTION

Type of 12:20 Semi-Annual Time: Date: 10/25/2021 Inspection: РМ Name of School Corporation: NORTH DAVIESS CO. COMM. SCHOOL 141375 Corp ID: **Address of School Corporation:** 5494 E SR 58 County City: Elnora Zip: 47529 14 Number: License VIN: 4UZABRCT77CW23659 22007 Bus Number: ND8 Number: Thomas Built Buses, Year: 2005 Thomas Built Buses, Year: Make of Make of Body: 2007 Inc. Chassis: Inc. **Bus Type:** С Mileage: Unknown Inspection Inspected R Philip Lubbers PE: 7703

Violations - Rejected

Status:

Inspection Code	<u>Description</u>
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired
43-1-8	Any required lettering is missing or faded.
13-1-1	Any clearance light is missing, cracked, faded, wrong color, or inoperative

By:

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.