

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Semi-Annual **Date:** 10/29/2021 **Time:** 11:04 AM
Name of School Corporation: PERU COMMUNITY SCHOOLS **Corp ID:** 525635
Address of School Corporation: 35 W 3rd St
City: Peru **Zip:** 46970 **County Number:** 52
VIN: 1GB6G2AG7A1167176 **License Number:** 84000 **Bus Number:** Tiger1
Make of Body: Starcraft **Year:** 2009 **Make of Chassis:** Chevrolet **Year:** 2010
Bus Type: A2 **Mileage:** 85717
Inspection Status: R **Inspected By:** Randy McPike **PE:** 7018

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
50-1-2	The seat belt cutter is not secured using a positive fastening method.

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.