

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Re-Inspection	Date: 11/1/2021	Time: 9:36 AM	
Name of School Corporation: NORTH DAVIESS CO. COMM. SCHOOL	Corp ID: 141375		
Address of School Corporation: 5494 E SR 58			
City: Elnora	Zip: 47529	County Number: 14	
VIN: 4DRBRABP13A955902	License Number: B208E	Bus Number: 6	
Make of Body: IC Corporation	Year: 2002	Make of Chassis: IC Corporation	Year: 2003
Bus Type: C	Mileage: Unknown		
Inspection Status: R	Inspected By: Philip Lubbers	PE: 7703	

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired
82-1-2	See Notes: Any defect inspector deems a violation not listed

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.