REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Semi-Annual			Date:	11/2/2021	Time:	12:12 PM
Name of School Co	orporation:	MARION	N COMMUNIT	Y SCHOOLS		Corp ID:	272865
Address of School	Corporation:	82	26 E 30th St				
City:	Marion	Zi	ip:	46952		County Number:	27
VIN:	4DRBUAAN19	B080404	4	License Number:	32355	Bus Number:	92
Make of Body:	IC Corporation	Year: 20	008	Make of Chassis:	IC Corporation	Year:	2009
Bus Type:	С			Mileage:	78182		
Inspection Status:	R	In	nspected By:	Randy McPike		PE:	7018

Violations - Rejected

Inspection <u>Code</u>	Description
28-1-4	The first aid kit is not complete: One (1) package adhesive bandages; containing a total of sixteen (16) 1" x 3" bandages, 1 roll 1"x5yd, 1 blunt scissor, 6 3x3" gauze pads (sterile), 4 2"x5yd gauze stretch material (nonsterile), 3 oval eye pads (sterile), 2 triangular bandages, 1 instruction.
70-1-10	If the emergency window instructions are illegible or missing. Must be within 6 inches of the release handle

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.