## **REPORT OF SCHOOL BUS INSPECTION**

Type of Inspection: Semi-Annual		Date:	11/3/2021	Time:	8:52 AM	
Name of School Corporation:		JTH DEARBORN	I COMM. SCH. COF	RP	Corp ID:	151600
Address of School	Corporation:	6109 Squire P	ace			
City:	Aurora	Zip:	47001		<b>County Number:</b>	15
VIN:	4DRBUAAN08B553	689	License Number:		Bus Number:	7
Make of Body:	IC Corporation Yea	r: 2008	Make of Chassis:	IC Corporation	Year:	2008
Bus Type:	В		Mileage:	136480		
Inspection Status:	R	Inspected By:	Chris Clark		PE:	6665

**Violations - Rejected** 

Inspection Code	Description
46-1-3	Any required padding is missing
41-1-4	There is debris in the bus. (needs cleaned/includes dirt)

Violations - Out of Service

Inspection Code Description

## **Bus Type Description**

Type B School Bus - A conversion or body constructed and installed upon a van or front-section vehicle chassis or stripped chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. Part of the engine is beneath and/or behind the windshield and beside the driver's seat. The entrance door is behind the front wheels.