

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	11/5/2021	Time:	11:39 AM
Name of School Corporation:	VIGO COUNTY SCHOOL CORPORATION	Corp ID:	848030		
Address of School Corporation:	3250 Maple Ave				
City:	Terre Haute	Zip:	47804	County Number:	84
VIN:	4DRBUC8N3NB321973	License Number:	NEW1973	Bus Number:	2129
Make of Body:	IC Corporation	Year:	2021	Make of Chassis:	IC Corporation
Year:	2022			PE:	7008
Bus Type:	C	Mileage:	1264		
Inspection Status:	O	Inspected By:	Byron Goodman		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails
64-1-2	A lens is cracked, missing or wrong color
33-1-2	The grill is missing
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.
82-1-2	The mirrors do not meet the outside mirror standard as set forth in 575 IAC 1-2-49

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
34-2-1	Both lamps are inoperative on low beam
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).
70-2-2	Any glass or glazing is cracked, chipped, clouded or distorted badly enough to prohibit a clear view from within the bus

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.