## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:Semi-AnnualDate:11/8/2021Time:11:27 AMName of School Corporation:CANNELTON CITY SCHOOLSCorp ID:626340

Address of School Corporation: 109 S 3rd St

City:CanneltonZip:47520County Number:62VIN:4UZABRDTXGCGT3394License Number:23668Bus Number:5Make of Body:Freightliner Year:2015Make of Chassis:Freightliner Year:2016

Bus Type: A1 Mileage: Unknown

Inspection Status: R Inspected By: Philip Lubbers PE: 7703

### Violations - Rejected

Inspection Code	<u>Description</u>
57-1-5	Step-well light is missing or inoperative
69-1-3	Wiper blades are torn, cracked, brittle or otherwise deteriorated
50-1-2	The seat belt cutter is not secured using a positive fastening method.

#### **Violations - Out of Service**

# **Inspection Code Description**

## **Bus Type Description**

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

- 1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
- 2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.