REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Semi-Annual	**Date:**	11/8/2021	**Time:**	11:27 AM
Name of School Corporation:	CANNELTON CITY SCHOOLS			**Corp ID:**	626340
Address of School Corporation:	109 S 3rd St				
City:	Cannelton	**Zip:**	47520	**County Number:**	62
VIN:	4UZABRDTXGCGT3394	**License Number:**	23668	**Bus Number:**	5
Make of Body:	Freightliner **Year:** 2015	**Make of Chassis:**	Freightliner	**Year:**	2016
Bus Type:	A1	**Mileage:**	Unknown		
Inspection Status:	R	**Inspected By:**	Philip Lubbers	**PE:**	7703

Violations - Rejected

Inspection Code	Description
57-1-5	Step-well light is missing or inoperative
69-1-3	Wiper blades are torn, cracked, brittle or otherwise deteriorated
50-1-2	The seat belt cutter is not secured using a positive fastening method.

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. **Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
2. **Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**