

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Semi-Annual Date: 11/8/2021 Time: 11:27 AM
Name of School Corporation: CANNELTON CITY SCHOOLS Corp ID: 626340
Address of School Corporation: 109 S 3rd St
City: Cannelton Zip: 47520 County Number: 62
VIN: 4UZABRDTXGCGT3394 License Number: 23668 Bus Number: 5
Make of Body: Freightliner Year: 2015 Make of Chassis: Freightliner Year: 2016
Bus Type: A1 Mileage: Unknown
Inspection Status: R Inspected By: Philip Lubbers PE: 7703

Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--|
| 57-1-5 | Step-well light is missing or inoperative |
| 69-1-3 | Wiper blades are torn, cracked, brittle or otherwise deteriorated |
| 50-1-2 | The seat belt cutter is not secured using a positive fastening method. |

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.