

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Post-Crash Inspection **Date:** 11/8/2021 **Time:** 9:35 AM
Name of School Corporation: PRAIRIE HEIGHTS COMM. SCH. COR **Corp ID:** 444515
Address of School Corporation: 305 S 1150 E
City: LaGrange **Zip:** 46761 **County Number:** 44
VIN: 1BAKFCJA6NF385093 **License Number:** temp **Bus Number:** 15
Make of Body: Blue Bird Corporation **Year:** 2021 **Make of Chassis:** Blue Bird Corporation **Year:** 2022
Bus Type: C **Mileage:** 4524
Inspection Status: O **Inspected By:** Wes Rowlander **PE:** 7427

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails
20-1-10	See Notes: Any defect inspector deems a violation not listed

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
70-2-1	Any glass or glazing is broken through or missing
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.