

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Semi-Annual	Date:	11/16/2021	Time:	12:29 PM
Name of School Corporation:	CRAWFORD CO. COMM. SCHOOL CORP			Corp ID:	131300
Address of School Corporation:	5808 E Administration Rd				
City:	Marengo	Zip:	47140	County Number:	13
VIN:	4DRBUAAP98A499509	License Number:	B851N	Bus Number:	7
Make of Body:	IC Corporation	Year:	2007	Make of Chassis:	IC Corporation
Year:	2008	Mileage:	Unknown	PE:	7703
Bus Type:	C	Inspected By:	Philip Lubbers		
Inspection Status:	R				

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
24-1-1	The bus body has rust or rusted through areas which may weaken the body
34-1-1	Any headlight is inoperative

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.