REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Semi-Annual			Date:	11/16/2021	Time:	12:33 PM
Name of School Corporation: Address of School Corporation:			CRAWFORD CO. COMM. SCHOOL CORP 5808 E Administration Rd			Corp ID:	131300
City:	Marengo	Ž	Zip:	47140		County Number:	13
VIN:	1BAKFCPA67F241	201		License Number:	B951B	Bus Number:	22
Make of Body:	Blue Bird Corporation	Year: 2	2006	Make of Chassis:	Blue Bird Corporation	Year:	2007
Bus Type:	С			Mileage:	Unknown		
Inspection Status:	R	_	Inspected By:	Philip Lubbers		PE:	7703

Violations - Rejected

Inspection Code	<u>Description</u>
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired
23-1-3	Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).
22-1-1	A dripping oil or fluid leak

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.