REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Semi-Annual		Date:	11/16/2021	Time:	12:48 PM
Name of School Co	orporation: (CRAWFORD CO. CC	MM. SCHOOL CO	RP	Corp ID:	131300
Address of School Corporation:		5808 E Adminis	stration Rd			
City:	Marengo	Zip:	47140		County Number:	13
VIN:	4DRBUAAP48B	3499525	License Number:	B346Q	Bus Number:	3
Make of Body:	IC Corporation	Year: 2006	Make of Chassis:	IC Corporation	Year:	2008
Bus Type:	A2		Mileage:	Unknown		
Inspection Status:	R	Inspected By:	Philip Lubbers		PE:	7703

Violations - Rejected

Inspection CodeDescription65-1-1Any lens is cracked, broken or discolored

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.

2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.