

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Semi-Annual	<b>Date:</b>	11/16/2021	<b>Time:</b>	12:59 PM
<b>Name of School Corporation:</b>	CRAWFORD CO. COMM. SCHOOL CORP	<b>Corp ID:</b>	131300		
<b>Address of School Corporation:</b>	5808 E Administration Rd				
<b>City:</b>	Marengo	<b>Zip:</b>	47140	<b>County Number:</b>	13
<b>VIN:</b>	1GBJG31K091163308	<b>License Number:</b>	81641	<b>Bus Number:</b>	85
<b>Make of Body:</b>	Collins Bus Corporation	<b>Year:</b>	2009	<b>Make of Chassis:</b>	Chevrolet
<b>Year:</b>	2009	<b>Year:</b>	2009	<b>Year:</b>	2009
<b>Bus Type:</b>	A1	<b>Mileage:</b>	Unknown		
<b>Inspection Status:</b>	R	<b>Inspected By:</b>	Philip Lubbers	<b>PE:</b>	7703

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
62-1-2	One (1) taillight or one (1) brake light does not function

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

### Bus Type Description

**Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:**

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.