REPORT OF SCHOOL BUS INSPECTION

| Type of Inspection: | Spot Checks | | Date: | 11/19/2021 | Time: | 9:14 AM |
|---------------------------------|--|--------------------------|----------------------|-----------------------------|-------------------|------------|
| Name of Schoo Address of Sch | I Corporation: NO ool Corporation: | RTH DAVIESS 5494 E SR | 8 CO. COMM. SC 58 | CHOOL | Corp ID: | 141375 |
| City: | Elnora | Zip: | 47529 | | County Number: | 14 |
| VIN: | 4UZABRDJ9ACAN3249 | | License Number: | B620Q | Bus Number: | 13 |
| Make of Body: | Thomas Built Buses, Yea Inc. | ır: 2009 | Make of Chassis: | Thomas Built Buses, Inc. | Year: | 2010 |
| Bus Type: | С | | Mileage: | Unknown | | |
| Inspection Status: | R | Inspected By: | Philip Lubbers | | PE: | 7703 |

Violations - Rejected

| Inspection <u>Code</u> | Description |
|---------------------------|---|
| 24-1-2 | The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails |

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.