# REPORT OF SCHOOL BUS INSPECTION

| | | | | | |
|---|---|---|---|---|---|
| **Type of Inspection:** | Semi-Annual | **Date:** | 11/29/2021 | **Time:** | 12:00 PM |
| **Name of School Corporation:** | ANDERSON COMM. SCHOOL CORP. | | | **Corp ID:** | 485275 |
| **Address of School Corporation:** | 1600 Hillcrest Ave | | | | |
| **City:** | Anderson | **Zip:** | 46011 | **County Number:** | 48 |
| **VIN:** | 4DRBUAAN5BB253251 | **License Number:** | ACS40 | **Bus Number:** | 40 |
| **Make of Body:** | IC Corporation **Year:** 2009 | **Make of Chassis:** | IC Corporation | **Year:** | 2011 |
| **Bus Type:** | C | **Mileage:** | 155155 | | |
| **Inspection Status:** | O | **Inspected By:** | Jeremy Mason | **PE:** | 8139 |

**Violations - Rejected**

| Inspection Code | Description |
|---|---|
| 50-1-2 | The seat belt cutter is not secured using a positive fastening method. |
| 57-1-5 | Step-well light is missing or inoperative |

**Violations - Out of Service**

| Inspection Code | Description |
|---|---|
| 65-2-1 | Warning lights fail to operate correctly |

**Bus Type Description**

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**