REPORT OF SCHOOL BUS INSPECTION

Type of 10:53 Semi-Annual 11/30/2021 **Time**: Date: Inspection: AM Name of School Corporation: **AVON COMMUNITY SCHOOLS** Corp ID: 323315 7203 E HWY 36 **Address of School Corporation:** County City: Avon Zip: 46123 32 Number: License VIN: 4UZAAXDC15CN93626 20404 **Bus Number:** 20 Number: Make of Thomas Built Buses, Year: 2004 Freightliner Year: 2005 Make of Body: Inc. Chassis: **Bus Type:** С Mileage: 130699 Inspection Inspected R PE: Joel Flores 7415 Status: By:

Violations - Rejected

<u>Inspection Code</u> <u>Description</u>

22-1-1 A dripping oil or fluid leak

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.