REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Spot Checks Date: 11/30/2021 Time: 1:11 PM

Name of School Corporation: GREENWOOD COMM. SCHOOL CORP.

Corp ID: 414245

Address of School Corporation: 605 W Smith Vally Rd

City:GreenwoodZip:46142County Number:41VIN:4DRBUSKPXCB556565License Number:1701Bus Number:21Make of Body:IC Corporation Year:2011Make of Chassis:IC Corporation Year:2011

Bus Type: C Mileage: 81224

Inspection Status: O Inspected By: Joel Flores PE: 7415

Violations - Rejected

| Inspection Code | <u>Description</u> |
|-----------------|--|
| 22-1-1 | A dripping oil or fluid leak |
| 20-1-10 | See Notes: Any defect inspector deems a violation not listed |
| 46-1-10 | See Notes: Any defect inspector deems a violation not listed |
| 79-1-5 | See Notes: Any defect inspector deems a violation not listed |
| 17-1-1 | Any dome light is inoperative |
| 47-1-3 | See Notes: Any defect inspector deems a violation not listed |
| 41-1-1 | There are objects blocking aisles or exits |

Violations - Out of Service

| Inspection Code | <u>Description</u> |
|--------------------|---|
| 41-2-1 | Interior is excessively dirty. (Excessive trash or dirt that would jeopardize the safety of students) |
| 8-2-1 | There is no brake certification, or the certification has expired or is not signed |

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.