

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	12/2/2021	Time:	11:33 AM
Name of School Corporation:	MARION COMMUNITY SCHOOLS	Corp ID:	272865		
Address of School Corporation:	826 E 30th St				
City:	Marion	Zip:	46952	County Number:	27
VIN:	1BAKGCSA2NF381182	License Number:	24722	Bus Number:	34
Make of Body:	Blue Bird Corporation	Year:	2020	Make of Chassis:	Blue Bird Corporation
Bus Type:	C	Mileage:	3724	Year:	2022
Inspection Status:	O	Inspected By:	Randy McPike	PE:	7018

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
24-1-7	See Notes: Any defect inspector deems a violation not listed
41-1-4	There is debris in the bus. (needs cleaned/includes dirt)
55-1-6	See Notes: Any defect inspector deems a violation not listed
67-1-2	Rims are bent or loose
61-1-5	See Notes: Any defect inspector deems a violation not listed

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)(Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district).
63-2-3	Any tire is flat

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.