REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Spot Checks	**Date:**	11/30/2021	**Time:**	1:11 PM
Name of School Corporation:	GREENWOOD COMM. SCHOOL CORP.			**Corp ID:**	414245
Address of School Corporation:	1542 Averitt Rd				
City:	Greenwood	**Zip:**	46142	**County Number:**	41
VIN:	4DRBUSKPXCB556565	**License Number:**	1701	**Bus Number:**	21
Make of Body:	IC Corporation **Year:** 2011	**Make of Chassis:**	IC Corporation	**Year:**	2011
Bus Type:	C	**Mileage:**	81224		
Inspection Status:	O	**Inspected By:**	Joel Flores	**PE:**	7415

Violations - Rejected

Inspection Code	Description
79-1-5	See Notes: Any defect inspector deems a violation not listed
22-1-1	A dripping oil or fluid leak
20-1-10	See Notes: Any defect inspector deems a violation not listed
46-1-10	See Notes: Any defect inspector deems a violation not listed
47-1-3	See Notes: Any defect inspector deems a violation not listed
17-1-1	Any dome light is inoperative
41-1-1	There are objects blocking aisles or exits

Violations - Out of Service

Inspection Code	Description
8-2-1	There is no brake certification, or the certification has expired or is not signed
41-2-1	Interior is excessively dirty. (Excessive trash or dirt that would jeopardize the safety of students)

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.